

NO  
OPERATIONS GROUP FILE

Pa →

LOGNOTE.....PANAMA BUREAU.....14 April 1986

B

[ ] Army Technician Nelson Smith spoke with me today to report on the progress (or lack of progress) in activating the bureau's Mode I Mux circuit. Smith said he still could not get the equipment to work on-line. He said, while he has not yet given up all hope, success could not be guaranteed.

STAT

Smith agreed to get in touch with ESG's [ ] to explain the technical details of the problems he faces activating our Mode I Mux Circuit. Smith also gave me two (2) pages of hand written notes and a one (1) page diagram to help explain the mode I circuit problem. Copies are attached.

STAT

Smith said he was departing Panama for CONUS on 15 April and had no plans at the present to return. Smith said he would continue to check with the Inteq Flatpack people and the "MC3" people to see if they could help resolve the Mode I problems.

Attachment  
as stated

cc: C/OPS ✓  
C/ESG  
C/FED/ESG  
C/FBIS Commo ✓


# 1. TIMING/LOST DATA PROBLEM

MC3 LEL (LOCAL EXTERNAL LOOPBACK)

GOOD

MC3 LIL (LOCAL INTERNAL LOOPBACK)

NO GOOD



MC3 CONTAINS A TRANSMIT AND RECEIVER PROCESSOR CARD.

- DATA LOSS OCCURS WHEN IN A LIL LOOPBACK.
- OSCILLOSCOPE (MONITORED AT INPUT/OUTPUT OF MC3) INDICATES CLOCKS DRIFTING.
- DATASCOPE INDICATES DATA LOSS IS DURING TRANSMISSION BY THE 3A-1.
- PROBLEM DOES NOT OCCUR ON 300 OR 1200 BAUD CIRCUITS.
- ASC TEST

2, 3A-1 REP TIMER 64 CHARACTERS (SOFTWARE)

3, RFS/TSO: MODE I  
SYNC  
CONTINUOUS  
BAUDOT 1TA2 (5 LEVEL)

INTEQ ADVISES THE 3A-1 INTERFACES AUTODIN IN  
ASCII (8 LEVEL). THE 3A-1 PRESENTLY GENERATES  
A "SOH A" SELECT CHARACTER AT START OF MESSAGE.  
SELECT "A" IS FOR BAUDOT. SELECT "H" IS FOR ASCII.  
(SOFTWARE)

SI + SO: VERIFY IF THESE ARE VALID FOR  
ASCII/MODE I.

4, RECEIVE ETX STOP: TAPE CONTINUES TO RUN  
DURING WRT STATUS.

5, 3A-1/MC3 COMPATIBLE AT 150 BAUD?

6, 300 BAUD: TERMINAL CONFIGURATION CHANGE.  
(PRINTER 150)

7 DCA CAT III TEST PLAN/TEST

**Page Denied**